




**Figure 2.1-1**  
Portland Harbor RI/FS  
Remedial Investigation Report  
Number of Observations of Radio-Tagged Chinook Salmon in  
Shallow Water and Deep Water Habitats between RM 3.5 and 11.7



**Figure 2.1-2**  
Portland Harbor RI/FS  
Remedial Investigation Report  
Multiplate Sampler Array


Winter 2002

Summer 2002




Difference Analysis

**Figure 2.1-3**  
Portland Harbor RI/FS  
Remedial Investigation Report  
Example of Winter and Summer 2002 Sun-Illuminated  
Images and Difference Analysis (DEA 2003a)



Note: Daily mean discharge values shown were downloaded from the USGS Real Time National Water Information System (NWIS) Database for the Morrison Bridge station 14211720 on March 6, 2009. Discharge values shown for October 1-31, December 16, February 24-27, and April 1-3 are estimated.

**Figure 2.1-4**  
 Portland Harbor RI/FS  
 Remedial Investigation Report  
 Upstream TSS Study Period Hydrograph and Sampling Dates



**Figure 2.2-1**  
 Portland Harbor RI/FS  
 Remedial Investigation Report  
 Schematic Willamette Riverbank  
 Cross Section, RM 2-11